

Occurrence Communication: Oc00164-2020 **Date:** 22/Sep/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145869
Marks: N694AE	Operator: ENVOY	Occurrence Date: 20/Sep/2020
Ata: 22	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of electrical odor and smoke in cockpit
The flight crew reported electrical odor and smoke coming from the first officer's control yoke during taxi.

Maintenance personnel removed and replaced the AP/TRIM/PUSHER Disc switch IAW AMM 22-11-07.
Subsequent operational check was satisfactory.