

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00177-2020 **Date:** 10/Nov/2020 Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145108
Marks: N622AE	Operator: ENVOY	Occurence Date: 04/Oct/2020
Ata : 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: X None Light:	0 Serious: 0 Fatal:	0
Occurence Description:		

Occurence Description:

Report of smoke in the cabin during cruise.

The flight crew reported receiving "PACK 1 VLV CLSD" advisory message on EICAS in cruise and the flight attendant reported smoke in cabin. They then declared emergency.

Maintenance personnel performed operational check as per E145 FIM 21-20-00-810-801-A. They found Pack 1 and Pack 2 inoperable. No smoke at this time.