

Occurrence Communication: Oc00184-2020**Date:** 03/Dec/2020

Page 1 of 1

Type: /

| | | |
|---|-----------------------------|---|
| Aircraft: EMB-145 | Model: EMB-145 LR | Serial Number: 145892 |
| Marks: N905JH | Operator: ENVOY | Occurrence Date: 30/Nov/2020 |
| Ata: 49 | Time: | Number of Persons Aboard: Not Available |
| Aircraft Damages: | | |
| Site: NOT AVAILABLE | | |
| Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0 | | |

Occurrence Description:

Report of smoke in the cockpit and cabin followed by APU fail message
The flight crew reported smoke in the cockpit and cabin. They also reported receiving an APU fail message and the APU auto shut down.

Maintenance personnel removed and replaced APU.