

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00002-2021 Date: 20/Jan/2021 Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145783
Marks:	Operator:	Occurence Date:
N665BC	PIEDMONT	04/Jan/2021
Ata : 72	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: BRADLEY INTL - WINDSOR LOCKS - CT - UNITED STATES		
Injuries: X None Light:	O Serious: O Fatal:	0
Occurence Description:		
Report of uncommanded engine IFSD during cruise The flight crew reported an uncommanded engine IFSD during cruise, with no abnormal indications prior to shutdown. An uneventful singe engine landing was performed at destination airport. Maintenance personnel found metal debris in the tail pipe.		