



## Aircraft Occurrences November 2019

Statistics reflect accident information entered into the computer by the Accident and Investigation Office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

Accident ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Circumstances	Type of operation
CA18/2/3/9833	04-11-2019	Piper 28-140	ZS-JLF	NC	Eagle Air private air strip	0	Pilot reported that during landing the aircraft right hand wing collided with a kudu.	Training
CA18/2/3/9834	11-11-2019	Piper 28-140	ZS-EXI	GP	Olympia road close to the airfield	0	The aircraft a Piper Cherokee 140, registration ZS-EXI lost engine power on short final approach during the third circuit.	Training
CA18/2/3/9835	15-11-2019	Jabiru J340	ZU-NEE	GP	Runway 09	0	During the landing roll of the fifth circuit on runway 09 the brakes failed, the aircraft over shot the runway	Training
CA18/2/3/9836	17-11-2019	Jabiru J160	ZU-FAT	GP	Rhino Park	0	The pilot reported that they were conducting circuits and on landing, there was a down draft which pushed the aircraft on to the runway and it landed hard. The nose gear was bent and the left main gear separated/broke off and the aircraft veered off to the left of the runway before stopping.	Private
CA18/2/3/9837	15-11-2019	CALIDUS	ZU-RLN	KZN	FANC	0	The pilot reported that during take-off, the gyro experienced a high-speed blade flapping and it rolled to its left side and came to rest resting on its left side.	General Aviation and Operating Flight Rules
CA18/2/3/9838	21-11-2019	CTSW	ZU-POT	WC	Runway 23 (Private farm)	0	The pilot stated that his approach speed was high and the aircraft kept on flying and they touched down deep on the runway with approximately 250m left for braking	Operation of Non-Type Certificated Aircraft (Part 94)
CA18/2/3/9839	28-11-2019	Bell 505	ZT-RDR	NC	14nm from FAKM	0	It was reported to the ATC that the helicopter had crashed 14nm from Kimberly. Helicopter was found with substantial damage and all occupants were seriously injured.	Private
CA18/2/3/9840	20-11-2019	GS-2 Sportsman	ZU-JVN	WC	Porterville private airstrip	0	It was reported that the aircraft ground looped during landing.	General Aviation and Operating Flight Rules
CA18/3/2/1291	08-11-2019	Cessna 550	ZS-CAR	GP	FALA Runway 24	0	Pilot reported he rejected the take-off on runway 24 FALA due to smoke in the cockpit.	Aerial survey
CA18/3/2/1292	29-11-2019	Cessna 206	ZS-EZK	EC	FAPE	0	On final approach, they heard a loud bang from the engine compartment followed by engine vibration and smoke in the cockpit.	General Aviation and Operating Flight Rules
CA18/3/2/1293	14-11-2019	B222U	ZS-HDI	GP	Kliprivier station	0	The pilot reported that engine number two started spooling down when passing abeam Kliprivier station. The pilot elected to execute a precautionary landing at Kromvlei airstrip.	Air Ambulance Operations
CA18/3/2/1294	02-11-2019	Zodiac 601XL	ZU-CUN	NC	5nm South of the Spitskop	0	The pilot reported that the propeller separated from the aircraft in flight and he executed a forced landing on an open field.	Private

083 461 4887

aaidin@caa.co.za

Last date of update: 13 December 2019