


<p style="text-align: center;">SOUTH AFRICAN</p>  <p style="text-align: center;">CIVIL AVIATION AUTHORITY</p>	<p><b>REPUBLIC OF SOUTH AFRICA</b></p> <p>CIVIL AVIATION AUTHORITY</p> <p><b>AERONAUTICAL INFORMATION CIRCULAR</b></p>	<p>CAA Private Bag x73 Halfway House 1685</p>
<p>Tel: (011) 545-1000 Fax: (011) 545-1465 E-Mail: mail@caa.co.za</p>		<p><b>AIC</b> <b>Series D</b> 019/2015 10 DEC 2015</p>

**AIR NAVIGATION SERVICES**

**GENERAL**

**NOTICE TO WITHDRAW HARTEBEESSPOORTDAM VOR (HBV)**

Hartebeespoortdam VOR HBV 112.1 MHz/CH90X located at S254032.98 E0274957.29 will be withdrawn on AIRAC Effective 4 February 2016.

The position with the same coordinates where HBV is located will receive a 5 Letter Name Code in the future.

The following procedures and Air Traffic Services (ATS) Routes will be affected:

**FALA**


- Lanseria INTL VOR Z RWY 07 Straight- in
- Lanseria INTL VOR Y RWY 07
- Lanseria INTL RNAV (GNSS) RWY 07

**FAWK**

- BRONKHORST 3C STAR 01
- HARTBEEES 2F STAR 01
- HARTBEEES 3D SID 01
- HARTBEEES 2G SID 01
- TEXON 1B SID 19 – Communications failure.
- BRONKHORST 3B SID 19
- HARTBEEES 3E SID 19

**ATS Routes**

- A405
- UA405
- G655
- UG655
- G853
- UG853
- G653
- UG653
- UB540
- UL435

  
 Acting  
**DIRECTOR OF CIVIL AVIATION**