

**Transport Canada Civil Aviation (TCCA)
Transports Canada, Aviation Civile (TCAC)**

Recently Issued Document / Document récemment publié

***The following notice is being re-sent in order to correct the link.**

***L'avis suivant est envoyé de nouveau afin de corriger le lien.**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: CF-1997-18R1

Subject: ATA 62 - Main Rotor System – Cracking of Rotor Mast

Applicability: Airbus Helicopters Deutschland GmbH (formerly Eurocopter) model BO105 LS A-3 helicopters

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-1997-18R1-E.pdf>

If you no longer wish to receive notifications related to ADs and Civil Aviation Safety Alerts (CASAs) or if you wish to request an e-mail address change, please notify TCCA at AD-CN@tc.gc.ca.

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) :

Numéro: CF-1997-18R1

Sujet: ATA 62 - Système de rotor principal – Fissuration du mât de rotor

Applicabilité: Les hélicoptères de modèle BO105 LS A-3 d'Airbus Helicopters Deutschland GmbH (auparavant Eurocopter)

Lien: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-1997-18R1-F.pdf>

Si vous ne désirez plus recevoir des avis concernant les CN et les alertes à la sécurité de l'Aviation civile (ASAC) ou si vous changez votre adresse électronique, veuillez aviser TCAC à AD-CN@tc.gc.ca.

Continuing Airworthiness / Maintien de la navigabilité aérienne

1-888-663-3639

AD-CN@tc.gc.ca

Transport Canada / Transports Canada

Email secured by Check Point

#####