The following Documents have been published or updated by EASA and may be of interest to you:

\* AD 2016-0084 - ROLLS-ROYCE PLC: SUPERSEDED BY EASA AD 2018-0088

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2016-0084

\* **AD** 2018-0088 - ROLLS-ROYCE PLC: Engine – Upper Bifurcation Fairing Seal Face – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0088

\* **AD** 2018-0087 - LEONARDO S.p.A. HELICOPTERS: Time Limits / Maintenance Checks – Airworthiness Limitation Section – Amendment / Implementation

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/2018-0087">http://ad.easa.europa.eu/ad/2018-0087</a>