

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0102 - AIRBUS: Wings – Rib 5 to Rear Spar Attachment – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0102>

* **PAD** 18-061 - ROLLS-ROYCE DEUTSCHLAND: Engine – Accessory Gearbox Module Attach Parts and Fittings / Mount Pins – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-061>

* **PAD** 18-062 - ROLLS-ROYCE PLC: Engine – Low Pressure Turbine Disc Seal Fins and Interstage Seals – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-062>
