

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2015-0016** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2018-0172

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0016>

* **AD 2018-0172** - AIRBUS HELICOPTERS: Main Rotor Blade Attachment Pin – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0172>

* **AD CF-2018-21** - BOMBARDIER: Wings – Cracked Spoiler Actuator Bracket

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-21>
