The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0065 - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2018-0272

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0065

* **AD** CF-2018-32 - BOMBARDIER: Auto Flight System – Airplane Flight Manual (AFM) Limitations and Abnormal Procedures – Velocity Decay during Low Level ALT CAP in One Engine Inoperative Conditions

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2018-32

* **AD** 2018-0272 - AIRBUS HELICOPTERS: Time Limits / Maintenance Checks — Main Gearbox / Particle Detectors — Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0272