The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2013-0184R2 - AIRBUS: Fuselage – Frame 47 Splice Fitting Holes Between Stringers 24 and 26 – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2013-0184R2

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/18-164">http://ad.easa.europa.eu/ad/18-164</a>

<sup>\*</sup> **PAD** 18-164 - AIRBUS HELICOPTERS: Fuselage – Main Gearbox Suspension Bar Rear Attachment Fitting Screws – Inspection