The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2018-0267 - AIRBUS: Wings – Movable Flap Track Fairing #2 U-Frame Bolt-Nut Couples – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0267

\* AD 2018-0268 - ROLLS-ROYCE DEUTSCHLAND: Engine – Life-Limited Critical Parts – Service Life Calculation / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/2018-0268</u>

\* **PAD** 18-170 - AIRBUS: Fuselage – Aft Fitting of Frame 40 – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/18-170</u>

\* **AD** CF-2018-31 - BOMBARDIER: Landing Gear System – Alternate Extension System – Introduction of New Airworthiness Limitation

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2018-31

\* PAD 18-171 - AIRBUS: Wings - Slat Tracks Number 10 - Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/18-171</u>

\* **PAD** 18-172 - AIRBUS: Oxygen – Oxygen Crew and Courier Distribution System Flexible Hoses – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/18-172

\* AD 2018-0269 - VULCANAIR S.p.A.: Wings – Center Wing Ribs – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/2018-0269</u>