

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2015-0059** - SAFRAN HELICOPTER ENGINES: SUPERSEDED BY EASA AD 2017-0040

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0059>

* **AD 2016-0033** - GUIMBAL, HELICOPTERES: SUPERSEDED BY EASA AD 2017-0039

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0033>

* **AD 2017-0039** - GUIMBAL, HELICOPTERES: Powerplant – Engine Cooling Fan – Modification / Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0039>

* **AD 2017-0040** - SAFRAN HELICOPTER ENGINES: Air – Inlet Guide Vane / Variable Stator Vane Actuator / Clevis Pin – Inspection / Re-Installation

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0040>