

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD NL-2005-003** - FOKKER SERVICES: CANCELLED – REPLACED BY EASA AD 2018-0015

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/NL-2005-003>

* **AD NL-1993-169-2** - FOKKER SERVICES: CANCELLED – REPLACED BY EASA AD 2018-0015 & EASA AD 2018-0016

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/NL-1993-169-2>

* **AD NL-1981-050** - FOKKER SERVICES: CANCELLED – REPLACED BY EASA AD 2018-0015

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/NL-1981-050>

* **AD 2010-0231** - CEAPR: CANCELLED – REPLACED BY EASA AD 2018-0017 and AD 2018-0018

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2010-0231>

* **AD 2012-0157** - DASSAULT AVIATION: SUPERSEDED BY EASA AD 2018-0021

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2012-0157>

* **AD 2015-0001R1** - AIRBUS: SUPERSEDED BY EASA AD 2018-0023

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0001R1>

* **CZIB 2015-02R2** - Conflict Zone Information Bulletin: CANCELLED: Replaced by EASA CZIB 2018-02

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-02R2>

* **AD 2015-0104** - SUKHOI CIVIL AIRCRAFT, JSC: SUPERSEDED BY EASA AD 2018-0020

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0104>

* **AD 2016-0067** - DASSAULT AVIATION: SUPERSEDED BY EASA AD 2018-0026

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0067>

* **AD 2016-0127** - DASSAULT AVIATION: SUPERSEDED BY EASA AD 2018-0027

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0127>

* **AD 2016-0117** - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2018-0028

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0117>

* **AD 2018-0023** - AIRBUS: Doors – Main Landing Gear Fixed Fairing Assembly - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0023>

* **AD 2016-0187** - AIRBUS: SUPERSEDED BY EASA AD 2018-0024

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0187>

* **AD F-1994-264R1** - SOCATA: SUPERSEDED BY EASA AD 2018-0030

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/F-1994-264R1>

* **AD 2018-0030** - SOCATA: Wings – Wing Front Attachments – Inspection / Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0030>

* **AD US-2017-07-02** - SIKORSKY: SUPERSEDED BY FAA AD 2018-02-13

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-07-02>

* **AD 2018-0024** - AIRBUS: Door – Forward and Aft Cargo Door Frame Forks – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0024>

* **AD 2018-0021** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0021>

* **AD 2018-0020** - SUKHOI CIVIL AIRCRAFT, JSC: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0020>

* **AD 2018-0026** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0026>

* **AD 2018-0022** - DASSAULT AVIATION: Ice and Rain Protection – Wing Anti-Ice System / Anti-Ice Pipe – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0022>

* **AD 2018-0027 - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment**

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0027>

* **AD 2018-0019 - ROLLS-ROYCE PLC: Engine – Critical Parts – Reduction of Declared Safe Cyclic Life**

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0019>

* **AD 2018-0017 - CEAPR: Landing Gear – Nose Landing Gear Oleo Outer Cylinder Support Plate – Inspection / Replacement**

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0017>

* **AD 2018-0018 - CEAPR: Landing Gear – Nose Landing Gear Oleo Outer Cylinder Support Plate – Inspection / Repair / Replacement**

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0018>

* **AD 2018-0015 - FOKKER SERVICES: Landing Gear – Main Landing Gear Drag Stay Tubes – Inspection / Replacement**

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0015>

* **AD 2018-0016 - FOKKER SERVICES: Landing Gear – Main Landing Gear Drag Stay Units – Inspection / Replacement**

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0016>

* **AD** 2018-0029 - TECNAM: Flight Controls – Rudder Trim Actuator – Life Limit Implementation

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0029>

* **AD** 2018-0031 - AIRBUS: Doors – Forward and Aft Cargo Door Frame Forks – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0031>

* **CZIB** CZIB-2018-02 - Conflict Zone Information Bulletin: [Correction] Airspace of Pakistan – Karachi and Lahore Flight Information Regions - Valid until 09 July 2018

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CZIB-2018-02>

* **AD** 2018-0028 - LEONARDO S.p.A. HELICOPTERS: Main Rotor Drive – Freewheel Lubrication System – Modification / Inspection / Cleaning

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0028>

* **AD** CF-2018-05 - BOMBARDIER: Landing Gear – Safety Device Modification at Nose Gear Retraction Actuator to Main Fitting Joint

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-05>

* **AD** US-2017-26-05 - GULFSTREAM AEROSPACE CORPORATION: Wings - Flap Track - Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-26-05>

* **PAD** 18-011 - AIRBUS: Fuselage – Belly Fairing and Keel Beam Side Panel Attachment Angles – Inspection / Replacement / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-011>

* **PAD** 18-010 - ROLLS-ROYCE PLC: Engine – Intermediate Pressure Compressor Rotor Shaft and Balance Weights – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-010>

* **AD** US-2018-02-14 - HONEYWELL INTERNATIONAL INC.: Engine - Combustion Chamber Case Assembly - Inspection / Replacement / Removal

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-02-14>

* **PAD** 18-012 - AIRBUS: Oxygen - Main Passenger Oxygen Distribution Line Flexible Hoses - Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-012>

* **PAD** 18-013 - AIRBUS: Equipment / Furnishings – Overhead Stowage Compartments – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-013>

* **SIB** 2018-03 - Safety Information Bulletin: Carriage and use of Automatic External Defibrillators

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-03>

* **AD** 2018-0025 - WSK PZL - SWIDNIK S.A.: Placards and Markings – Installation / Rotorcraft Flight Manual – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0025>

* **AD** US-2018-02-13 - SIKORSKY: Main Rotor Drive - Drive Shaft - Repetitive Inspections / Life Limitation

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-02-13>