The following Documents have been published or updated by EASA and may be of interest to you:

* **SIB** 2016-18R1 - Safety Information Bulletin: Dynamic Rollout during Hoisting and/or External Sling Load Operations

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/2016-18R1</u>

* AD 2018-0152 - AIRBUS HELICOPTERS: Fuselage – Main Gearbox Bracket Bolts – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/2018-0152</u>

* **PAD** 18-098 - AIRBUS: Exhaust – Thrust Reverser Outer Fixed Structure – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/18-098</u>