

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD F-2005-115** - AIRBUS: SUPERSEDED BY EASA AD 2018-0135

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/F-2005-115>

---

\* **AD 2014-0058** - AIRBUS: SUPERSEDED BY EASA AD 2018-0135

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2014-0058>

---

\* **AD 2018-0135** - AIRBUS: Landing Gear – Main Landing Gear Sliding Tube – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0135>

---

\* **PAD 18-087** - ROLLS-ROYCE PLC: Engine – High Pressure Turbine Disc Front Cover Plate – Replacement [Life Limitation]

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-087>