

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2007-0057R1 - SAFRAN HELICOPTER ENGINES: Engine – Gas Generator Front Bearing – Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2007-0057R1>

---

\* **PAD** 18-020R1 - ROLLS-ROYCE DEUTSCHLAND: Engine – Low Pressure Compressor Fan Blades – Identification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-020R1>

---

\* **PAD** 18-043 - AIRBUS: Wings – Top Skin Stringer Joints at Rib 19 – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-043>