

The following Documents have been published or updated by EASA and may be of interest to you:

* **EAD** 2018-0250-E - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2018-0252-E

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0250-E>

* **PAD** 18-159 - LEONARDO S.p.A. HELICOPTERS: Windows – Passenger Windows – Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-159>

* **PAD** 18-160 - CFM INTERNATIONAL: Engine – Fan Blades – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-160>

* **EAD** 2018-0252-E - LEONARDO S.p.A. HELICOPTERS: Tail Rotor – Tail Rotor Flight Control System – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0252-E>