

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD US-2010-25-06** - BOEING: SUPERSEDED BY FAA AD 2018-19-20

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2010-25-06>

* **AD US-2018-18-13** - BOEING: Wings - Outboard Flap Tracks - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-18-13>

* **AD US-2018-18-03** - BOEING: Doors / Fuselage - Floor Beam Lower Chord and Door Stop Fittings - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-18-03>

* **AD US-2018-19-20** - BOEING: Fuselage - Frames and Stub Beams - Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-19-20>

IMPORTANT NOTICE

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section