

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** ISR-I-24-2018-09-7 - GULFSTREAM (GALP): Electrical Power - Upper and Lower Front Relay Box Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/ISR-I-24-2018-09-7>

* **AD** CF-2018-24 - BOMBARDIER: Cold Weather Operations – Introduction of Low Ground Temperature Wing Anti-Ice Procedure

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-24>

* **PAD** 18-133 - AIRBUS: Flight Controls – Flap / Slat Torque Shafts – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-133>

IMPORTANT NOTICE

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section