

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** US-2018-14-12 - GENERAL ELECTRIC: Engine - Air / Oil Extension Duct - Removal / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-14-12>

* **PAD** 18-110 - AIRBUS HELICOPTERS: Tail Rotor – Blade – Life Limit / Re-identification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-110>

* **PAD** 18-111 - AIRBUS HELICOPTERS: Tail Rotor – Blade – Life Limit / Re-identification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-111>

* **SIB** CE-18-23 - Safety Information Bulletin: F. Atlee Dodge Aircraft Services LLC. Folding Jump Seats - Passenger Compartment Equipment - Installation of Folding Jump Seats in a variety of Textron Aviation, Inc. (Cessna) airplanes

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CE-18-23>
