

21 December 2017



Continuing Airworthiness Sections
National Civil Airworthiness Authorities
ICAO Contracting States

Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8.

The following Airworthiness Directive is issued by the New Zealand Civil Aviation Authority who is the responsible state of design national airworthiness authority for the product in accordance with ICAO Annex 8.

DCA/750XL/23 Cockpit Control Handles – Inspection

This AD is prompted by a ground inspection which found it is possible for the control column to snag on the cockpit control tee handles on certain aircraft. When the tee handle is pulled out to the maximum limit it fouls with the control column in the extreme forward right and left positions. The tee handles are mounted below the switch panels adjacent to the centre console.

This AD with effective date 28 December 2017 mandates the inspection and corrective actions per the Accomplishment Instructions in Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/093 issue 1, dated 15 December 2017, or later approved revision.

A copy of DCA/750XL/23 is attached. NZ ADs applicable to 750XL aircraft are available from the CAA web site at

http://www.caa.govt.nz/assets/legacy/Airworthiness_Directives/750XL.pdf

Yours faithfully

A handwritten signature in black ink, appearing to read 'Owen Olls', is written over a light grey rectangular background.

Owen Olls
Airworthiness Specialist

Phone +64 4 560 9569 UTC + 12

Fax +64 569 2024

owen.olls@caa.govt.nz