

22 March 2018



Continuing Airworthiness Sections
National Civil Airworthiness Authorities
ICAO Contracting States

Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8.

The following Airworthiness Directive is issued by the New Zealand Civil Aviation Authority who is the responsible state of design national airworthiness authority for the product in accordance with ICAO Annex 8.

DCA/750XL/24A Pitot Static Tube Support Clamps – Inspection

This AD with effective date 22 March 2018 mandates the inspection and corrective actions in Pacific Aerospace Service Bulletin (SB) PACSB/XL/094 issue 2, dated 20 March 2018, or later approved revision.

This SB revised to include inspection information, and DCA/750XL/24A updated to introduce the revised SB. The AD is prompted by a production inspection of installed pitot static plumbing which identified insufficient clearance between the pitot tubes and the primary support at the flame arrestor intersection.

A copy of DCA/750XL/24A is attached. NZ ADs applicable to 750XL aircraft are available from the CAA web site at

http://www.caa.govt.nz/assets/legacy/Airworthiness_Directives/750XL.pdf

Yours faithfully

A handwritten signature in black ink, appearing to read 'Owen Olls', is written over a light grey rectangular stamp area.

Owen Olls
Airworthiness Specialist

Phone +64 4 560 9569 UTC + 12

Fax +64 569 2024

owen.olls@caa.govt.nz