

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0185 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: SUPERSEDED BY EASA AD 2019-0101

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0185>

* **AD** 2019-0101 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Powerplant – Breather Drains Mast Assembly – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0101>

* **SIB** BEA-2017-02 - Safety Information Bulletin: Embraer EMB-135, EMB-145, ERJ-170 and ERJ-190 Aeroplanes - Software ePerfManager or other not certified software

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/BEA-2017-02>

* **PAD** 19-080 - AIRBUS: Wings – Lower Skin Covers at Rib Bay 3/4 – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-080>