

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD US-2019-16-15** - PRATT & WHITNEY: Engine - High-Pressure Compressor Front Hub - Revision of the Airworthiness Limitations Section and the Continued Airworthiness Maintenance Programs

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-16-15>

* **AD US-2019-13-05** - SIKORSKY: Fuselage - Main Transmission Forward and Aft Frame Assemblies and Adjacent Skins - Inspections

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-13-05>

* **AD US-2019-15-07** - BOEING: Fuselage - Fuselage Lower Lobe Frames - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-15-07>

* **AD US-2019-14-15** - BOEING: Fuselage - Stub Beams - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-14-15>