

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: CF-2019-27

Subject: **ATA 53 - FUSELAGE – STRUCTURAL FAILURE**

Applicability: GA8 AIRVAN PTY LTD MODEL GA8 AND GA8-TC 320 AEROPLANES

Link: <https://www.wapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-27-E.PDF>

Number: CF-2019-28

Subject: **FLIGHT CONTROLS – SWASHPLATE ASSEMBLY – IMPROPERLY STAKED BEARINGS**

Applicability: Bell Helicopter Textron Canada Limited (BHTCL) model 505 helicopters

Link: <https://www.wapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-28-E.PDF>

Number: CF-2019-27R1

Subject: **ATA 53 - FUSELAGE – STRUCTURAL FAILURE**

Applicability: GA8 AIRVAN PTY LTD MODEL GA8 AND GA8-TC 320 AEROPLANES

Link: <https://www.wapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-27R1-E.PDF>

You are receiving this notification as a subscriber to the Transport Canada Civil Aviation e-Bulletin alert service. To unsubscribe, please use the form available on this Web page:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/menu-1152.htm>

For further information on **e-Bulletin**, you may wish to visit:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/managementservices-referencecentre-menu-113.htm> .

You can also contact Transport Canada's Civil Aviation Communications Centre at 1-800-305-2059 or at services@tc.gc.ca for questions regarding this service.

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) :

Numéro: CF-2019-27

Sujet: **ATA 53 - FUSELAGE – DÉFAILLANCE STRUCTURALE**

Applicabilité: LES AVIONS DE GA8 AIRVAN PTY LTD. MODÈLE GA8 ET GA8-TC 320

Lien: <https://www.wapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-27-F.PDF>

Numéro: CF-2019-28

Sujet: **COMMANDES DE VOL – PLATEAU CYCLIQUE – ROULEMENTS MAL SERTIS**

Applicabilité: Les hélicoptères de Bell Helicopter Textron Canada Limited (BHTCL) modèle 505

Lien: <https://www.wapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-28-F.PDF>

Numéro: CF-2019-27R1

Sujet: **ATA 53 - FUSELAGE – DÉFAILLANCE STRUCTURALE**

Applicabilité: LES AVIONS DE GA8 AIRVAN PTY LTD. MODÈLE GA8 ET GA8-TC 320

Lien: <https://www.wapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-27R1-F.PDF>

Vous recevez cet avis électronique à titre d'abonné au service d'alerte par courriel de Transports Canada Aviation civile. Si vous désirez vous désabonner, veuillez utiliser le formulaire disponible à cette page Web : <http://www.tc.gc.ca/fra/aviationcivile/opssvs/menu-1152.htm>

Pour autres informations reliées au bulletin électronique, vous pouvez visiter : <http://www.tc.gc.ca/fra/aviationcivile/opssvs/servicesdegestion-centredereference-menu-113.htm>. Vous pouvez contacter le Centre de communications de l'Aviation civile de Transports Canada au 1-800-305-2059 ou services@tc.gc.ca pour toutes questions à l'égard de ce service

#####