The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2019-0184 - AIRBUS HELICOPTERS: Rotors Flight Control – Main Rotor Servo Actuators – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0184

\* AD DCA-750XL-38 - PACIFIC AEROSPACE LTD: Flap Assembly Screw Jack — Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/DCA-750XL-38">https://ad.easa.europa.eu/ad/DCA-750XL-38</a>