The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2019-0188 - AIRBUS: Hydraulic Power – Hydraulic Reservoir Air Pressurization System Lines – Functional Tests

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0188

\* **AD** 2019-0190 - AIRBUS: Hydraulic Power – Hydraulic Reservoir Air Pressurization System Lines – Functional Tests

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2019-0190">https://ad.easa.europa.eu/ad/2019-0190</a>

\* AD 2019-0171R1 - AIRBUS: Aircraft Flight Manual Section Limitations – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2019-0171R1">https://ad.easa.europa.eu/ad/2019-0171R1</a>

\* AD 2019-0189 - AIRBUS: Aircraft Flight Manual Section Limitations – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0189

\* **EAD** 2019-0191-E - WSK PZL - SWIDNIK S.A.: Equipment / Furnishings — Hoist Carrier Assembly Bracket / Bolts — Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2019-0191-E">https://ad.easa.europa.eu/ad/2019-0191-E</a>