

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0281** - AIRBUS HELICOPTERS: Fuselage – ADF Antenna / Fuel Tank Protection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0281>

* **AD BR-2019-11-07** - EMBRAER: Landing Gear - Pintle Pin of the Main Landing Gear Shock Struts - Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/BR-2019-11-07>

* **AD 2019-0282** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Intermediate Pressure Compressor Shaft Assembly – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0282>

* **EAD 2019-0284-E** - AIRBUS DEFENCE & SPACE GmbH: Wings – Inner Flap Fitting Bearing Bolts – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0284-E>
