The following Documents have been published or updated by EASA and may be of interest to you:

\* EAD 2019-0055-E - BRP-ROTAX GmbH & Co KG: SUPERSEDED BY EASA AD 2019-0253-E

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2019-0055-E">https://ad.easa.europa.eu/ad/2019-0055-E</a>

\* **EAD** 2019-0253-E - BRP-ROTAX GmbH & Co KG: Engine fuel and Control – Fuel Pump Assembly – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2019-0253-E">https://ad.easa.europa.eu/ad/2019-0253-E</a>

\* **PAD** 19-189 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Low Pressure Compressor Front Cases – Removal from Service

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/19-189">https://ad.easa.europa.eu/ad/19-189</a>

\* **AD** US-2019-20-07 - BOEING: Flight Controls - Leading Edge Outboard Slats - Operational Checks; Airplane Flight Manual - Amendment

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/US-2019-20-07">https://ad.easa.europa.eu/ad/US-2019-20-07</a>