

The following Documents have been published or updated by EASA and may be of interest to you:

\* **EAD** 2019-0237-E - DG-FLUGZEUGBAU: Cabin Systems – Canopy Lock / Rear Locking Rods – Inspection / Check / Repair Aircraft Flight Manual – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0237-E>

---

\* **PAD** 19-174 - SAAB AB: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-174>

---

\* **AD** CF-2019-33 - BOMBARDIER: Landing Gear – Trailing Arm Assembly Axle Bore Corrosion

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2019-33>

---