

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD US-2019-18-09** - LOCKHEED MARTIN CORPORATION: Wings - Center Wing Upper and Lower Rainbow Fittings - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-18-09>

* **PAD 19-181** - PIAGGIO: Aircraft Flight Manual – Amendment; Navigation – Flight Environment Data / Altimetry System for RVSM Operations – Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-181>

* **AD CF-2019-34** - BELL HELICOPTER TEXTRON CANADA (BHTC): Tail Rotor Drive – Failure of tail rotor drive shaft coupling bolted connections

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2019-34>

* **AD US-2019-18-03** - BOEING: Exhaust - Thrust Reverser Upper Locking Actuators - Maintenance Instructions Amendment / Integrity Testing

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-18-03>

IMPORTANT NOTICE

The 7th EASA Airworthiness Directives (AD) Workshop will be held on **25-26 November 2019**