

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0137R1 - AIRBUS: Nacelles / Pylons – Pylon Aft Fixed Fairings – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0137R1>

* **AD** 2018-0265R1 - BRP-ROTAX GmbH & Co KG: Engine – Exhaust Valve – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0265R1>

* **PAD** 19-002 - AIRBUS HELICOPTERS DEUTSCHLAND: Airworthiness Limitation Section – TT-Straps – Storage Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-002>

* **PAD** 19-003 - AIRBUS: Flight Controls – Flight Control Primary Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-003>

* **PAD** 19-004 - SOLO KLEINMOTOREN GmbH: Engine – Propeller Reduction Gear Excentric Axle Bearings – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-004>