

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00002-2019 Date: 04/Jan/2019

Page 1 of 1

Type: Serious Incident

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145846
Marks:	Operator:	Occurence Date:
N687JS	ENVOY	31/Dec/2018
Ata: 00	Time: 5:58 AM	Number of Persons Aboard: 14
Aircraft Damages:		
Site: Alexandria Intl - Al	EXANDRIA - LA - UNITED STATES	
Injuries: 🗙 None	Light: 0 Serious: 0	Fatal: ⁰

Occurence Description:

Report of runway excursion during landing

It was reported that the aircraft veered off the runway during landing. The aircraft collided with runway signs and came to a stop with the right main gear off the paved surface of the runway abeam of turnoff taxiway A2 about 1600 meters/5300 feet down the runway. The passengers disembarked onto the runway and were taken to the terminal. There are no reports of injuries to the people on board. According to the METAR the weather was foggy visibility was 1/2 Statute Miles (804 meters)