

**Occurrence Communication:** Oc00094-2019**Date:** 07/Mar/2019

Page 1 of 1

**Type: Accident**

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-145 XR	<b>Serial Number:</b> 145859
<b>Marks:</b> N14171	<b>Operator:</b> COMMUTAIR	<b>Occurrence Date:</b> 04/Mar/2019
<b>Ata:</b> 00	<b>Time:</b>	<b>Number of Persons Aboard:</b> 31
<b>Aircraft Damages:</b> Pictures indicate the landing gears collapsed. They also indicate that the left main landing gear separated from the aircraft and became lodged between the fuselage and the left engine.		
<b>Site:</b> NORTHERN MAINE REGL AT PRESQU* - PRESQUE ISLE - ME - UNITED STATES		
<b>Injuries:</b> <input type="checkbox"/> None <b>Light:</b> 3 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of landing off the runway under snow conditions  
It was reported that the aircraft landed to the right side of the runway, out of the paved surface, under snow conditions. Preliminary information indicates minor injuries to 3 passengers. The aircraft sustained substantial damage.

**ADDITIONAL INFORMATION:**

This event is under investigation by the NTSB.