

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00105-2019 Date: 22/Mar/2019

Page 1 of 1

Type: Major Event

Aircraft:	Мо	del:	Serial Number:
EMB-145	EM	B-145 XR	145872
Marks: N14173	-	erator: PRESSJET	Occurence Date: 19/Mar/2019
Ata: 21	Tim	e:	Number of Persons Aboard: Not Available
Aircraft Damages:			
Site: NOT AVAILABLE			
Injuries: X None	Light: 0	Serious: ⁰	Fatal: 0

Occurence Description:

Report of smoke in the cockpit and cabin during cruise The flight crew reported smoke in the cockpit and cabin during cruise.

Maintenance personnel found ACM 1 seized. They then removed and replaced it. Subsequent operational checks were satisfactory.