

**Occurrence Communication:** Oc00125-2019      **Date:** 10/Apr/2019

Page 1 of 1

**Type: Major Event**

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-135 LR	<b>Serial Number:</b> 145651
<b>Marks:</b> N838AE	<b>Operator:</b> ENVOY	<b>Occurrence Date:</b> 08/Apr/2019
<b>Ata:</b> 21	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> LEHIGH VALLEY INTL - ALLENTOWN - PA - UNITED STATES		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of smoke on board  
The flight crew reported smoke in the cabin. They noticed that the origin was from rear to the middle of the aircraft, with a strong burning smell.