

**Occurrence Communication:** Oc00160-2019      **Date:** 09/May/2019

Page 1 of 1

**Type:** /

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-145 LR	<b>Serial Number:</b> 145079
<b>Marks:</b> N612AE	<b>Operator:</b> TRANS STATES	<b>Occurrence Date:</b> 07/May/2019
<b>Ata:</b> 21	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> MIAMI INTL - MIAMI - FL - UNITED STATES		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of decompression followed by masks deployment.  
The flight crew reported decompression at FL250. Oxygen masks were deployed and cabin altitude started to raise slowly.