

31 January 2019



Continuing Airworthiness Sections
National Civil Airworthiness Authorities
ICAO Contracting States

Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8.

The following Airworthiness Directive is issued by the New Zealand Civil Aviation Authority who is the responsible state of design national airworthiness authority for the product in accordance with ICAO Annex 8.

DCA/750XL/34 Port Wing Internal Tank Abrasion – Inspection

Air Transport Association (ATA) Chapter 28, Fuel System.

DCA/750XL/34 with effective date 7 February 2019 is prompted by a report of finding chafing damage in the port wing skin caused by the fuel filter filters. The AD is issued to introduce inspection and repair requirements with the issue of Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/099 issue 1, dated 16 January 2019.

A copy of DCA/750XL/34 is attached. NZ ADs applicable to 750XL aircraft are available from the CAA web site at

http://www.caa.govt.nz/assets/legacy/Airworthiness_Directives/750XL.pdf

Yours faithfully

A handwritten signature in black ink, appearing to read 'Owen Olls', is written over a light grey rectangular background.

Owen Olls
Airworthiness Specialist

Phone +64 4 560 9569 UTC + 12
Fax +64 569 2024
owen.olls@caa.govt.nz