Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* SIB CE-19-01 - Safety Information Bulletin: Textron Aviation Inc. Model 172R, 172S, 182S, 182T, T182T, 206H, T206H Airplanes - Engine Oil Pressure Switch

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CE-19-01

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-024

^{*} PAD 19-024 - AIRBUS: Landing Gear – Free Fall Actuators – Inspection / Replacement