

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2015-0020** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2020-0095

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2015-0020>

* **SD SD-2020-01** - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/SD-2020-01>

* **SD SD-2020-02** - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/SD-2020-02>

* **AD 2020-0095** - AIRBUS HELICOPTERS: Doors – Sliding Door Star Support – Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0095>

* **PAD 20-070** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/20-070>

* **PAD 20-073** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/20-073>