The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** US-2020-07-51 - INTERNATIONAL AERO ENGINES AG: [Final Rule] Engine - High Pressure Turbine 1st-Stage Disks - Removal

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/US-2020-07-51">https://ad.easa.europa.eu/ad/US-2020-07-51</a>

\* **SIB** SAFO20006 - Safety Information Bulletin: Boeing 787 Aeroplanes - Vacuum-Type Fall-Arrest Protection Systems and Paint Peeling Issues

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/SAFO20006

\* SIB NM-20-06 - Safety Information Bulletin: Boeing 787 Aeroplanes - Electrical Power System - Lug Terminal Tracks

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/NM-20-06