The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2020-0008 - DIAMOND AIRCRAFT INDUSTRIES: Flight Controls — Flap Control System / Bellcrank Assembly — Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2020-0008">https://ad.easa.europa.eu/ad/2020-0008</a>

\* EAD US-2020-01-55 - GENERAL ELECTRIC: Engine - Interstage Seals - Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/US-2020-01-55">https://ad.easa.europa.eu/ad/US-2020-01-55</a>

\* PAD 20-011 - AIRBUS: Flight Controls – Spoiler Servo Control / Hydraulic Locking Function – Operational Test

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/20-011">https://ad.easa.europa.eu/ad/20-011</a>