

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: CF-2020-01

Subject: ATA 28 - FUEL SYSTEM – NON-CONFORMING INSTALLATION OF ELECTRICAL BONDING JUMPERS

Applicability: De Havilland Aircraft of Canada Limited (formerly Bombardier Inc.) model DHC-8-400, DHC-8-401 and DHC-8-402 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2020-01-E.PDF>

You are receiving this notification as a subscriber to the Transport Canada Civil Aviation e-Bulletin alert service. To unsubscribe, please use the form available on this Web page:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/menu-1152.htm>

For further information on **e-Bulletin**, you may wish to visit:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/managementservices-referencecentre-menu-113.htm> .

You can also contact Transport Canada's Civil Aviation Communications Centre at 1-800-305-2059 or at services@tc.gc.ca for questions regarding this service.

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) :

Numéro: CF-2020-01