The following Documents have been published or updated by EASA and may be of interest to you:

\* AD CF-2019-33R1 - BOMBARDIER: Landing Gear – Trailing Arm Assembly Axle Bore Corrosion

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/CF-2019-33R1</u>

\* **AD** 2020-0016 - AIRBUS: Pneumatic – Engine Bleed Air Supply System High Pressure Valves – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2020-0016</u>

\* **AD** 2020-0011 - LEONARDO S.p.A. HELICOPTERS: [Correction] Main Rotor Drive - Main Gearbox Bearing Lock Nut – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2020-0011</u>