The following Documents have been published or updated by EASA and may be of interest to you:

\* AD US-2019-23-12 - BOEING: Wings - Fuel Tanks - Modification

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/US-2019-23-12</u>

\* AD US-2019-22-09 - BOEING: Fuselage - Main Landing Gear Aft Hanger Link Lug Fittings - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/US-2019-22-09</u>

\* **PAD** 20-001 - AIRBUS HELICOPTERS: Tail Rotor – Tail Rotor Hub Pitch Control Rod – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/20-001</u>