

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD F-2004-031R1** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2020-0021

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/F-2004-031R1>

---

\* **AD 2020-0021** - AIRBUS HELICOPTERS: Tail Rotor – Tail Rotor Hub Pitch Control Rod – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0021>

---