The following Documents have been published or updated by EASA and may be of interest to you:

\* AD 2019-0193 - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2020-0048

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2019-0193">https://ad.easa.europa.eu/ad/2019-0193</a>

\* **AD** 2020-0048 - LEONARDO S.p.A. HELICOPTERS: Tail Rotor — Tail Rotor Servo Actuator / Duplex Bearing — Inspection / Check / Modification

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2020-0048">https://ad.easa.europa.eu/ad/2020-0048</a>