The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2020-0103 - AIRBUS: [Correction] Equipment / Furnishings – Emergency Locator Transmitter Protection – Modifications

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2020-0103">https://ad.easa.europa.eu/ad/2020-0103</a>

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/2020-08">https://ad.easa.europa.eu/ad/2020-08</a>

<sup>\*</sup> SIB 2020-08 - Safety Information Bulletin: [Correction] DECOMATIC Titanium Bolts